WEEKLY BUILD SCHEDULE

SHOW: *BY THE WAY, MEET VERA STARK* **BLD WK:** 5TH (LOAD-IN)

	MON 9/3	TUES 9/4	WED 9/5	THURS 9/6	FRI 9/7
8:30 - 10:00	----------	-LEVEL 3 STUDWALLS -LEVEL 2 STUDWALLS	-PUT UP PANEL UNIT 1 -PUT UP PANEL UNIT 2	-FINISH ANY MASKING THAT DIDN'T GET DONE	- CATCH ALL – FINISH ANY SMALL DETAIL BITS NOT FINISHED
10:00 - 12:00	----------	-LEVEL 1 STUDWALLS -LEVEL 3 TRISCUITS -RUN CABLE FOR LEVEL 2	-PUT UP PANEL UNIT 3 -PUT UP PANEL UNIT 4 -BEGIN LAYING OUT INSULATION	-BEGIN PUTTING ON FACING	- CATCH ALL – FINISH ANY SMALL DETAIL BITS NOT FINISHED
1:00 - 2:00	**NO WORKERS**	-LEVEL 2 TRISCUITS -LEVEL 3 TRISCUITS	**NO WORKERS**	-CONTINUE FACING	- CATCH ALL – FINISH ANY SMALL DETAIL BITS NOT FINISHED
2:00 – 4:00	**NO WORKERS**	-RUN LED TAPE ON BOTTOM OF PLATFORMS	**NO WORKERS**	-CONTINUE FACING -GET STAIR UNITS IN PLACE AND SECURED	- CATCH ALL – FINISH ANY SMALL DETAIL BITS NOT FINISHED
4:00 – 5:00	**NO WORKERS**	-RUN LED TAPE ON BOTTOM OF PLATFORMS	**NO WORKERS**	-GET PORTAL UNIT IN -FINISH FACING	- CATCH ALL – FINISH ANY SMALL DETAIL BITS NOT FINISHED
6:00 - 10:00	----------	**NOT AN EVENING CALL**	-FINISH LAYING OUT INSULATION AND MASO CAP -PUT UP HARD MASKING -PUT UP SOFT MASKING	**NOT AN EVENING CALL**	**NOT AN EVENING CALL**
NOTES					